

ERA24LA189

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward view of aircraft at wreckage site. (Courtesy of FAA)



Photograph 2 - Right side view of crashed airplane (Courtesy of FAA)