



Photo 1 – View of Airplane as Found (RDU)



Photo 2 – Rear View of Airplane as Found (RDU)



Photo 3 – View of Propeller Assembly after Recovery (RDU)



Photo 4 – View of Pavement Striations Perpendicular to Runway Centerline (RDU)



Photo 5 – Close View of Pavement Striations Perpendicular to Runway Centerline (RDU)



Photo 6 – View of Right Main Landing Gear as Found (RDU)