

ERA24LA198

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at the accident site. (Courtesy of FAA)



Photograph 2 - View of fuselage damage.



Photograph 3 - View of floor damage.