

ERA24LA202

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of left side of aircraft in the grass (Courtesy of Pilot)



Photograph 2 - Postaccident view of left-wing damage (Courtesy of Pilot)



Photograph 3 - Collapsed left main landing gear (Courtesy of FAA)