



Photo 1 – View of Helicopter as Found (HCSO)



Photo 2 – View of Wrinkled Tailboom, Vertical Stabilizer, and Separated T/R Gearbox (HCSO)




Photo 3 – View of Dismounted and Damaged No. 1 T/R Driveshaft Bearing (HCSO)



Photo 4 – View of Hanger Bearing Support Bracket with Displaced Elastomeric Bushing (HCSO)



Photo 5 – View of Separated T/R Gearbox (HCSO)



Photo 6 – View of Tailrotor Hub and Blade Assembly (HCSO)



Photo 7 – View of Separated Red T/R Blade as Found (HCSO)