

ERA24LA214

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane Off Runway (Courtesy of FAA)



Photograph 2 - Right Wing Damage (Courtesy of FAA)



Photograph 3 - Right Wing Damage (Courtesy of FAA)



Photograph 4 - Lower Fuselage Damage (Courtesy of FAA)



Photograph 5 - Landing Gear Extension Handle Deployed (Courtesy of FAA)