

ERA24LA215

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to Helicopter Tail (Courtesy of Pilot)



Photograph 2 - Left Side View of Damage (Courtesy of Pilot)