

ERA24LA223

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aerial View of Accident Site (Courtesy of LCMCD)



Photograph 2 - Aerial View of Accident Site (Courtesy of LCMCD)



Photograph 3 - Main Wreckage (Courtesy of LCMCD)



Photograph 4 - Main Wreckage (Courtesy of LCMCD)



Photograph 5 - Main Wreckage (Courtesy of LCMCD)



Photograph 6 - Main Wreckage (Courtesy of LCMCD)



Photograph 7 - Main Wreckage (Courtesy of LCMCD)



Photograph 8 - Dried Fish Pond (Courtesy of LCMCD)



Photo 9 - Main Wreckage (Courtesy of LCMCD)



Photograph 10 - Left Engine and Propeller (Courtesy of LCMCD)



Photograph 11 - Right Engine and Propeller (Courtesy of LCMCD)