

ERA24LA225

INVESTIGATIVE PHOTOS



Photograph 1 - inverted airplane front view (Courtesy of FAA)



Photograph 2 -Inverted airplane rear view (Courtesy of FAA)



Photograph 3 - Vertical and rudder damage (Courtesy of FAA)



Photograph 4 - Wing rib damage (Courtesy of FAA)