

ERA24LA226

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of airplane on runway (Courtesy of Atlanta Air Salvage)



Photograph 2 - View of skid damage through skin to stringers and frames (Courtesy of FAA)



Photograph 3 - View of skid damage through skin to stringers and frames (Courtesy of FAA)