

ERA24LA248

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Atlanta Air Recovery)



Photograph 2 - Main Wreckage (NTSB Photo)



Photograph 3 - Forward Fuselage and Engine (NTSB Photo)



Photograph 4 - Wings (NTSB Photo)



Photograph 5 - Fuel Shutoff T-Handle (NTSB Photo)



Photograph 6 - Fuel Shutoff Valve (NTSB Photo)



Photograph 7 - Fuel Shutoff Valve (NTSB Photo)



Photograph 8 - Fuel Shutoff Valve (NTSB Photo)