

ERA24LA249

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Wing Leading Edge Damage (Courtesy of Flight School)