

ERA24LA250

## INVESTIGATIVE PHOTOS




**Photograph 1 - Left side vertical stabilizer with missing rivet (Courtesy of Skyborne)**



**Photograph 2 - Right side Vertical stabilizer with missing rivet (Courtesy of Skyborne)**



**Photograph 3 - Aft mounting bracket, 17 fractured rivets (Courtesy of Skyborne)**



**Photograph 4 - Vertical Stabilizer, note: fractured rivets (Courtesy of Skyborne)**