


ERA24LA252

INVESTIGATION PHOTOGRAPHS



Photograph 1 –Overview of damage to the right side of the airplane. (Courtesy of FAA)



Photograph 2 –Overview of the airplane at the accident site. (Courtesy of FAA)