

ERA24LA255

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at Accident Site (Courtesy of J. Auman)



Photograph 2 - Damage to Right Wing (Courtesy of FAA)



Photograph 3 - Front View of Airplane Damage (Courtesy of FAA)



Photograph 4 - Left Side View of Airplane (Courtesy of FAA)