

ERA24LA260

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view left side of airplane showing damage to nose wheel (Courtesy of FAA)



Photograph 2 - Underside of airplane showing damage to the fuselage (Courtesy of FAA)