

ERA24LA272

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Side of Airplane (Courtesy of Pilot)



Photograph 2 - Hull Damage (Courtesy of Pilot)



Photograph 3- Left Side of Airplane (Courtesy of Pilot)