

ERA24LA273

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Impact damage to left wing (Courtesy of pilot)



Photograph 2 - Impact damage to left wing (Courtesy of pilot)



Photograph 3 - Impact damage to left wing (Courtesy of pilot)