

ERA24LA275

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane on the runway. (Courtesy of Pilot)



Photograph 2 - View of damage to the nose of the airplane. (Courtesy of FAA)



Photograph 3 - View of damage to the nose of the airplane. (Courtesy of FAA)