

ERA24LA276

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident site overview (Source: FAA)



Photograph 2 - Fuselage overview (Source: FAA)




Photograph 3 - Engine overview at the accident site (Source: FAA)



Photograph 4 - Engine overview at the accident site (Source: FAA)




Photograph 5 - Engine overview



Photograph 6 - No. 1 exhaust riser



Photograph 7 - No. 1 exhaust riser end



Photograph 8 - No. 3 exhaust riser



Photograph 9 - No. 3 exhaust riser end



Photograph 10 - No. 3 exhaust riser spring attach loop



Photograph 11 - No. 2 exhaust riser



Photograph 12 - No. 2 exhaust riser end



Photograph 13 - No. 2 exhaust spring



Photograph 14 - No. 4 exhaust riser



Photograph 15 - No. 4 exhaust riser end