

ERA24LA280

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane and wing damage. (Courtesy of Pilot/Owner)



Photograph 2 - Closeup of leading edge wing damage. (Courtesy of Pilot/Owner)