


ERA24LA291


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Drone image of glider in tree canopy (Courtesy of FAA)



Photograph 2 - Glider in tree canopy with visible damage to right wing (Courtesy of FAA)



Photograph 3 - Glider in tree canopy with visible damage to right wing (Courtesy of FAA)