

ERA24LA295

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of bird impact (Courtesy of pilot)



Photograph 2 - Postaccident view of bird impact (Courtesy of pilot)



Photograph 3 - Bird impact damage from flight deck (Courtesy of pilot)