

ERA24LA296

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right side view of aircraft at wreckage site. (Courtesy of FAA)



Photograph 2 - left side view of crashed airplane (Courtesy of FAA)