

ERA24LA299

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane wreckage at accident site. (Courtesy of FAA)



Photograph 2 - Damage to No. 3 cylinder. (Courtesy of FAA)