

ERA24LA302

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fire Damage (FAA Photo)



Photograph 2 - Loose Fuel Line B-Nut (FAA Photo)