

ERA24LA306

INVESTIGATION PHOTOGRAPHS



Photograph 1 –Overview of the airplane. (Courtesy of FAA)



Photograph 2 – View of the damage to the right wing. (Courtesy of FAA)



Photograph 3 – View of the damage to the right wing. (Courtesy of FAA)