

ERA24LA307

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to Bulkhead (Courtesy of FAA)



Photograph 2 - Airplane Overview (Courtesy of FAA)