

ERA24LA311

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage at accident site (Courtesy of FAA)



Photograph 2 - Deformation noted to fuselage (Courtesy of FAA)