

ERA24LA312

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of wreckage (Courtesy of FAA)



Photograph 2 - Postaccident view of wreckage (Courtesy of FAA)



Photograph 3 - Postaccident view of wreckage (Courtesy of FAA)




Photograph 4 - Postaccident view of wreckage (Courtesy of FAA)



Photograph 5 - Postaccident view of wreckage from runway (Courtesy of FAA)



Photograph 6 - Right main landing gear tire (Courtesy of mechanic)



Photograph 7 - Disassembled right brake caliper (Courtesy of mechanic)



Photograph 8 - Disassembled right brake caliper (Courtesy of mechanic)



Photograph 9 - Right brake piston (Courtesy of mechanic)