

ERA24LA315

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of airplane showing damage to left wing (Courtesy of FAA)



Photograph 2 - View of left elevator showing damage (Courtesy of FAA)