

ERA24LA317

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 – Airplane at accident site (Courtesy of FAA)**



**Photograph 2 – Airplane after recovery (Courtesy of the pilot)**



**Photograph 3 – Damage to the fuselage (Courtesy of the pilot)**