

ERA24LA320

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Wing Root External Damage (Courtesy of FAA)



Photograph 2 - Left Wing Spar Damage (Courtesy of FAA)