



Photo 1 – Aft Quartering View of Airplane as Found (FAA)



Photo 2 – Front Quartering View of Airplane as Found (FAA)



Photo 3 – View of Wrinkled Cabin Structure (FAA)




Photo 4 – View of Fractured Nose Landing Gear (N/L/G) Mount Structure Attached to Separated N/L/G (FAA)