

ERA24LA336

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of airplanes' collision (Courtesy of Skyborne Airlines)



Photograph 2 - Postaccident view of airplanes' collision (Courtesy of Skyborne Airlines)



**Photograph 3 - Postaccident view of low-wing's wing broken through high-wing's window
(Courtesy of Skyborne Airlines)**



Photograph 4 - Damage to low-wing airplane's wing (Courtesy of Skyborne Airlines)



Photograph 5 - Damage to low-wing airplane's wing (Courtesy of Skyborne Airlines)



Photograph 6 - Damage to high wing airplane's window (Courtesy of Wayman Aviation)



Photograph 7 - Damage to high wing airplane's window (Courtesy of Wayman Aviation)