

ERA24LA350

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Aft Fuselage and Empennage (Courtesy of FAA)



Photograph 3 - Propeller Damage (Courtesy of FAA)