

ERA24LA355

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the left side of the fuselage. (Courtesy of FAA)



Photograph 2 - View of damage to the left side of the fuselage. (Courtesy of FAA)