


ERA24LA356

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Postaccident view of airplane (Courtesy of FAA)



Photograph 2 - Right wing impact damage (Courtesy of FAA)



Photograph 3 - Right wing impact damage (Courtesy of FAA)



Photograph 4 - Postaccident view of airplane right wing damage (Courtesy of FAA)