

ERA24LA361

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane On-Scene (Courtesy of Aircraft Recovery)



Photograph 2 - Airplane as First Viewed Prior to Examination



Photograph 3 - Evidence of Contaminated Fuel from Fuel Strainer



Photograph 4 - Debris is the Bottom of the Fuel Strainer