

ERA24LA364

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage buckling impact damage (Courtesy of FAA)



Photograph 2 - Fuselage buckling impact damage (Courtesy of FAA)



Photograph 3 - Floorboard buckling impact damage (Courtesy of FAA)



Photograph 4 - Floorboard buckling impact damage (Courtesy of FAA)