

ERA24LA366

INVESTIGATION PHOTOGRAPHS



Photograph 1 - FAA Digital Photograph. Right Side View of the Airplane at the Accident Site



Photograph 2 - FAA Digital Photograph. Left Rear Quartering View of the Airplane At the Accident Site. Note the Compression Wrinkles in the Left Side of the Fuselage



Photograph 3 - FAA Digital Photograph. Right Rear Quartering View of the Airplane At the Accident Site. Note the Compression Wrinkles in the Right Side of the Aft Fuselage



Photograph 4 - FAA Digital Photograph. View of the Nearly Completely Fractured Left Wing