

ERA24LA367

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Airplane at accident site (Source: FAA)




Photograph 2 - Airplane at accident site (Source: FAA)



Photograph 3 - Engine overview



Photograph 4 - Diaphragm fuel pump and fuel lines




2024/11/20 10:57

Photograph 5 - Carburetor and airbox



Photograph 6 - Carburetor bowl and jets



Photograph 7 - Carburetor floats, mixture control, and accelerator pump