

ERA24LA369

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane nose down resting inverted against a tree. (Courtesy of FAA)



Photograph 2 - Buckled fuselage resting against a tree. (Courtesy of FAA)



Photograph 3 - Right wing suspended in a tree above the airplane. (Courtesy of FAA)