

ERA24LA378

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane Overview (Courtesy of FAA)



Photograph 2 - View of Right Wing Damage (Courtesy of FAA)



Photograph 3 - View of Right Wing Damage (Courtesy of FAA)