

ERA24LA381

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward View of Airplane (Courtesy of FAA)



Photograph 2 - Damage to Right Wing (Courtesy of FAA)



Photograph 3 - Damage to Vertical Stabilizer and Rudder (Courtesy of FAA)