

ERA24LA382

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of basket and balloon. (Courtesy of Pilot/Owner)**



**Photograph 2 - Damaged balloon and cables. (Courtesy of Pilot/Owner)**



**Photograph 3 - View of balloon and wires at the site. (Courtesy of Pilot/Owner)**