


ERA24LA385

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Tailwheel Strut (Courtesy of FAA)



Photograph 3 - Tailwheel Strut Close-up (Courtesy of FAA)