

ERA24LA396

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane at the Scene (Courtesy of FAA)



Photograph 2 - Damage to the Left Wing (Courtesy of FAA)



Photograph 3 - Damage to the Left Wing (Courtesy of FAA)