


ERA24LA398

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Lower fuselage impact damage (Courtesy of Flight School)



Photograph 2 - Internal structure impact damage (Courtesy of Flight School)



Photograph 3 - Lower fuselage impact damage (Courtesy of Flight School)