

ERA25FA037

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (NTSB Photo)



Photograph 2 - Cockpit Area and Firewall (NTSB Photo)



Photograph 3 - Engine and Propeller (NTSB Photo)



Photograph 4 - Right Wing (NTSB Photo)



Photograph 5 - Aft Fuselage (NTSB Photo)



Photograph 6 - Empennage (NTSB Photo)



Photograph 7 - Left Wing Outboard Section (NTSB Photo)



Photograph 8 - Tree Branches (NTSB Photo)



Photograph 9 - Engine (NTSB Photo)



Photograph 10 - Vacuum Pump (NTSB Photo)



Photograph 11 - Top Spark Plugs (NTSB Photo)